


# Exploded

H3005 Lateral Raise



please note :parts didn't demolitionde part and fasteners not listde on the introduction

序号	名称	数量
D4	Foam Frame P1002	1
D3	Pin φ8*50	8
D2	Socket Cap inner hex M10*16	2
C19	Outer hex screw M12*80	4
C15	Self lock nut M12	4
C2	Flat washer φ10	8
C1	Cup head inner hex screw M8*35	8
A21	Spring washer φ12	22
A19	Outer hex screw M12*35	14
A16	Gasket DQ003	22
A15	Screw cap S208	22
A6	Cup head inner hex screw M5*15	8
A5	Cup head cross tapping screw ST3*8	4
A3	Top cover	1
A2	Back shroud	1
A1	Front shroud	1
12	Bearing fixing	1
10	Cam frame	2
09	Handle frame	2
08	Working arm	2
07	Pulley set frame	1
06	Seat fixing frame	1
05	Cusion selection	1
04	Main frame	1
03	Bottom connector	1
02	Bent frame set	1
01	Door frame	1