

Exploded

H3001 Prone curved leg training dev

please note :parts didn't demilitione part and fast
eners not listide on the introduction

C7	Flat washer Φ10	2
C6	self lock nut M10	2
C5	Sink inner hex screwM10*70	2
C4	Sink inner hex screw M10*25	2
C3	Snap head Inner hex screw M8*80	4
C2	Flat washerΦ8,3*Φ20*11.5	12
C1	Snap head Inner hex screw M8*35	8
B	weight stack set	1
A32	Dowel pinΦ8*50	2
A23	Gasket DN003 Φ29, 8*Φ12*14	10
A22	Spring washerΦ12	10
A21	Screw cap S208	10
A20	Outer hex screw M12*35	10
A6	Cup head inner hex screw M5*15	8
A5	Cup head cross tapping screw S13*8	4
A3	Top cover	1
A2	Back shroud	1
A1	Front shroud	1
T13	Handle	1
T08	Back connection set	1
T07	working arm	1
T06	Big cam	1
T03	Bottom connector	1
T02	Main frame	1
01	Door frame	1
serial number	name	quantity

