


# Exploded

## E3062 Seated Calf

please note :prats didn't demolitionne part and fasteners not listrde on the introduction



B20	Outer hex screw M12*25	4
B8	Flat washer φ 10	8
B7	Cup head inner hex screw M8*80	8
B4	Flat washer φ 10	4
B3	Socket cap inner hex screw M10*20	4
A9	Nylon cover	2
A8	Outer hex screw M12*20	2
A7	Big washer φ 30*11.5	2
A4	Gasket DM003	8
A3	Spring washer φ 12	8
A2	Screw cap S208	8
A1	Outer hex screw M12*35	2
13	Sleeve set	1
12	Bottom connector	1
11	Leg pressing cushion	2
10	Cushion	1
06	Connector	1
04	Leg pressing frame	1
03	Seat frame	1
02	Locating frame	1
01	Main frame	1
serial number	name	quantity